

??????? ????? Precitec (OG Y D37 D7, P0595-58601)

Item Code: CS-FB-PW37D7



FOB Price: ???.14 507/??.

Mini Order: 1 ??.

Average Rating: 0.2lb (0.1kg)

Inquire Now

Overview


????????? ???????? Precitec (OG Y D37 D7; P0595-58601)

????????: ??? ??????? Precitec ProCutter

???????:


?????? ???????: 10c? x 9c? x 8c?

??? ??????: 0,1??



High Precision of Production

No Seams in the Cavity of Cutting Head



High Mechanical Strength


The lens with high mechanical strength can stand with high power of laser beam.





It is dust-free and avoids its focus shaking during cutting as it influences the cutting quality.

Using poor quality protective lens will not only influence its cutting quality but also it is easy to damage the focusing lens. When we do maintenance service for customers, it often happens that there is dust entered the cavity due to poor quality of lens size which results the lens burned (as shown in the red circle on the photo right)



Troubles Attributed to Non-Original Protective Lens.


- 1. Poor quality of media coating will cause the lens easy to be burned by metal spark flyings.
- 2. Poor precision of lens where there is dust easier entering the cavity of cutting head will cause focusing lens damage.




Focusing Lens Damage




Poor Quality of Media Coating



Dust on Lens



























Copyright © 1999-2012 by Beijing ChinaSigns Information Company Limited All Rights Reserved.

Email:info@sign-in-global.com Tel:+86 132 6410 3286 www.sign-in-global.com